

CABLE TRAINING AND IDENTIFICATION

NOTE: Applies ONLY to transformers 500 kVA and greater AND 12 or more runs of 500 kcmil or larger cables.

The requirements for cable training and identification are shown below.

- The cable shall extend a minimum of 7 feet above the transformer pad.
- Each cable shall be marked with colored tape to indicate its phase.
- All cables shall be bundled together by phase.
- Cables shall be secured to the cable ladder rungs; zip ties are acceptable.

